

WisDOT Official List of Qualified Industry and Consultant Laboratories 02/10/2012

Name and Address	Sampling/Testing and Related Activities Performed	Application Date	Effective Date	Expiration Date
<p>AECOM 1035 Kepler Drive Green Bay, WI 54311-8320</p> <p>Robert J. Peeters bob.peeters@aecom.com 920-406-3130</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: T166.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 16, 2011	January 1, 2012	December 31, 2012
<p>AECOM 558 North Main Street Oshkosh, WI 54901</p> <p>Craig LeNoble Craig.lenoble@aecom.com 920-236-6720</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T24, T119, T152-Air Content, T152-Air Meter Calibration, T231, T309.</p> <p>Soils: T88, T89, T90, T99, T180, T224, T265, ASTM D 1140.</p>	December 16, 2011	January 1, 2012	December 31, 2012
<p>AECOM 200 Indiana Avenue Stevens Point, WI 54481</p> <p>Dick Kirchner Richard.kirchner@aecom.com 715-342-3043</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T119, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 1140.</p>	December 16, 2011	January 1, 2012	December 31, 2012

<p>AECOM W8009 Hwy 33 East Beaver Dam, WI 53916</p> <p>Craig LeNoble Craig.Lenoble@aecom.com 920-236-6720</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p>	<p>December 16, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>AECOM 750 Corporate Woods Parkway Vernon Hills, IL 60061</p> <p>Bill Quinn Bill.quinn@aecom.com 847-279-2500</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 21, 2010</p>	<p>January 1, 2011</p>	<p>December 31, 2011</p>
<p>American Engineering Testing, Inc. 4431 W. Michigan St. Suite 4 Duluth, MN 55807</p> <p>Andrew E. Edlund aedlund@amengtest.com 218-628-1518</p>	<p>Aggregate: Fracture (Coarse agg.), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>November 16, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>American Engineering Testing, Inc. 4203 Schofield Avenue Suite #1 Schofield, WI 54476</p> <p>Gregory C. Owens gowens@amengtest.com 715-359-3534</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T277, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>November 30, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>American Engineering Testing, Inc. 4203 Schofield Avenue Suite #1 Schofield, WI 54476</p> <p>Trailer Lab W-1</p> <p>Gregory C. Owens gowens@amengtest.com 715-359-3534</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152-Air Content, T152-Aggregate Correction, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 1140.</p>	<p>November 30, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>American Engineering Testing, Inc. 4203 Schofield Avenue Suite #1 Schofield, WI 54476</p> <p>Trailer Lab W-2</p> <p>Gregory C. Owens gowens@amengtest.com 715-359-3534</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T27, T89, T90, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152-Air Content, T152-Aggregate Correction, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 1140.</p>	<p>November 30, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>American Engineering Testing, Inc. 4203 Schofield Avenue Suite #1 Schofield, WI 54476</p> <p>Trailer Lab W-3</p> <p>Gregory C. Owens gowens@amengtest.com 715-359-3534</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 1140.</p>	<p>November 30, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>American Engineering Testing, Inc. 4203 Schofield Avenue Suite #1 Schofield, WI 54476</p> <p>Trailer Lab W-4</p> <p>Gregory C. Owens gowens@amengtest.com 715-359-3534</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152-Air Content, T152-Aggregate Correction, T198, T231, T309, R39.</p> <p>Soils: T89, T90, T99, T180, T224, T265, ASTM D 1140.</p>	<p>November 30, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>American Engineering Testing, Inc. 1837 CTH OO Chippewa Falls, WI 54729-6519</p> <p>Joel J. Guanella JGuanella@amengtest.com 715-861-5045</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104, AMRL Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 22, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>American Engineering Testing, Inc. 1837 CTH OO Chippewa Falls, WI 54729</p> <p>Mobile # 1</p> <p>Joel J. Guanella Joel.guanella@tetrattech.com 715-861-5045</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 22, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>American Engineering Testing, Inc. 1837 CTH OO Chippewa Falls, WI 54729</p> <p>Mobile # 2</p> <p>Joel J. Guanella Joel.guanella@tetrattech.com 715-861-5045</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 22, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>B. R. Amon & Sons W2950 Hwy. 11 Elkhorn, WI 53121</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>December 13, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>B.R. Amon & Sons W2950 Hwy 11 Elkhorn, WI 53121</p> <p>Trailer Lab #: 183.</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>December 13, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>B.R. Amon & Sons W2950 Hwy 11 Elkhorn, WI 53121</p> <p>Trailer Lab #: 181, 185.</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p>	<p>December 13, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>B.R. Amon & Sons W2950 Hwy 11 Elkhorn, WI 53121</p> <p>Trailer Lab #: 1341</p> <p>Joseph R. Kyle jkyle1@hotmail.com 262-741-5174</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, T166, T209, T269, T312.</p>	<p>December 13, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Bacco Construction Company P.O. Box 458 N3660 N U.S. 2 Iron Mountain, MI 49801</p> <p>Brian Vuorinen brianv@baccoconstruction.com 906-774-4064</p>	<p>Aggregate: WisDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 29, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Bacco Construction Company N3660 N U.S. 2 Iron Mountain, MI 49801</p> <p>Trailer Lab #1551.</p> <p>Brian Vuorinen brianv@baccoconstruction.com 906-774-4064</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 29, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Bacco Construction Company N3660 N U.S. 2 Iron Mountain, MI 49801</p> <p>Trailer Lab #1555.</p> <p>Brian Vuorinen brianv@baccoconstruction.com 906-779-1686</p>	<p>Aggregate: WisDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 29, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Barron County Highway Department 260 North 7th Street Barron, WI 54812</p> <p>Trailer #423-L</p> <p>John Dietrich Sandra.perry@co.barron.wi.us 715-637-3755</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>December 13, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Barron County Highway Department- Crusher 260 North 7th Street Barron, WI 54812</p> <p>Trailer # 319H</p> <p>Jeff Outcalt Sandra.perry@co.barron.wi.us 715-637-3755</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p>	<p>December 13, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Bay Area Testing and Consulting, LLC 1220 Hurlbut Street Green Bay, WI 54303</p> <p>Trailer Lab</p> <p>Jake Franzmeier Jake.franzmeier@gmail.com 920-660-5246</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D 4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D422, ASTM D 1140.</p>	<p>December 27, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Bloom Companies, LLC 600 W. Fulton Street Suite 701 Chicago, IL 60661</p> <p>Marla Weiss mweiss@bloomcos.com 312-876-9500</p>	<p>Aggregate: T11, T89, T90, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T152-Air Meter Calibration, T309.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D422.</p>	<p>November 17, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>CGC, Inc. * 2921 Perry Street Madison, WI 53713</p> <p>Kim J. Lewis klewis@cgcinc.net 608-288-4100</p>	<p>Aggregate: WisDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104. AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T88, T89, T90, T99, T180, T224, T265, ASTM D422.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>CGC, Inc. 336 S. Curtis Rd. West Allis, WI 53214</p> <p>Jeff Simkowski cgcmlw@cgcinc.net 414-443-2000</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T88, T99, T180, T224, T265, ASTM D422, ASTM D 1140.</p>	December 1, 2011	January 1, 2012	December 31, 2012
<p>Cemstone Materials Lab 1370 Troutbrook Circle St. Paul, MN 55117</p> <p>Kim-Tien Nguyen nrgc@cemstone.com 651-688-9292</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T231, T309, R39.</p>	December 5, 2011	January 1, 2012	December 31, 2012
<p>Cemstone Ready Mix Lab New Richmond Plant 1190 County Road G New Richmond, WI 54017</p> <p>Dave Horejsi dhorejsi@cemstone.com 715-243-1916</p>	<p>Aggregate: Fracture (Coarse agg.), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309, R39.</p>	December 5, 2011	January 1, 2012	December 31, 2012
<p>Chosen Valley Testing, Inc. 135 Buchner Place La Crosse, WI 54603</p> <p>Kraig McCoy kmccoy@chosenvallytesting.com 608-782-5505</p>	<p>Aggregate: WisDOT Fracture (Coarse agg). AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 6, 2011	January 1, 2012	December 31, 2012

<p>Cooper Engineering Company, Inc. 2600 College Drive P.O. Box 230 Rice Lake, WI 54868-0230</p> <p>Stan Stoeberl ssstoeberl@cooperengineering.net 715-234-7008</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Content, T152-Air Meter Calibration, T231, T309, R39.</p> <p>Soils: T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>November 22, 2012</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>County Materials Corporation 205 North Street Marathon, WI 54448</p> <p>Mike Strong Mike.strong@countymaterials.com 715-443-6261</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309, R39.</p> <p>Soils: T88, ASTM D 1140.</p>	<p>November 18, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>County Materials -Holmen 120 Union St. Holmen, WI 54636</p> <p>Mike Strong Mike.strong@countymaterials.com 715-551-8259</p>	<p>Aggregate: AASHTO T2 (WISDOT Modified), T11, T27, T248, T255.</p>	<p>November 30, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>County Materials Corporation 1203 70th Ave Roberts, WI 54023</p> <p>Chuck Kroll Chuck.kroll@countymaterials.com 715-749-2274</p>	<p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309, R39.</p>	<p>December 7, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Duffek Sand & Gravel, Inc. (Lab #1) 1625 West Center Street Antigo, WI 54409</p> <p>Brian T. Braun Brian@duffekinc.com 715-653-7616</p>	<p>Aggregate: WISDOT Fracture (Coarse), AASHTO T2 (WISDOT Modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Soils: T89, T90, T99, T180.</p>	<p>December 19, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Duffek Sand & Gravel, Inc. (Lab #2) 1625 West Center Street Antigo, WI 54409</p> <p>Brian T. Braun Brian@duffekinc.com 715-623-7616 X 238</p>	<p>Aggregate: WISDOT Fracture (Coarse), AASHTO T2 (WISDOT Modified), T11, T27, T248, T255, ASTM D4791.</p>	<p>December 19, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Duffek Sand & Gravel, Inc. (Lab #3) 1625 West Center Street Antigo, WI 54409</p> <p>Brian T. Braun Brian@duffekinc.com 715-623-7616 X 238</p>	<p>Aggregate: WISDOT Fracture (Coarse), AASHTO T2 (WISDOT Modified), T11, T27, T248, T255, ASTM D4791.</p>	<p>December 19, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Faulks Bros. Construction, Inc. E3481 Royalton St. Waupaca, WI 54981</p> <p>Brian Buchholz brian@waupacasand.com 715-258-8566</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T90, T248, T255, ASTM D4791.</p>	<p>November 29 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>F Radandt Sons Hwy Q-Pit 12415 Highway Q Two Rivers, WI 54241</p> <p>Josh Radandt fradandtsons@lakefield.net 920-755-2131</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T90, T248, ASTM D4791.</p>	<p>October 5, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>GeoTest, Inc. * 2135 S. 116th Street West Allis, WI 53227</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability-WisDOT Test Method, AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 26, 2011	January 1, 2012	December 31, 2012
<p>GeoTest, Inc. W6243 Constructor Dr. Unit A Appleton, WI 54914</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T89, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T224, T265, ASTM D422, ASTM D 1140.</p>	December 26, 2011	January 1, 2012	December 31, 2012
<p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #2</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T89, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152-Air Content, T152-Aggregate Correction, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 26, 2011	January 1, 2012	December 31, 2012

<p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #3</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T89, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 26, 2011	January 1, 2012	December 31, 2012
<p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #4</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p>	<p>Aggregate: A WISDOT fracture (coarse), ASHTO T2 (WISDOT Modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422.</p>	December 26, 2011	January 1, 2012	December 31, 2012
<p>GeoTest, Inc. 2135 S. 116th Street West Allis, WI 53227</p> <p>Mobile Lab #6</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p>	<p>Aggregate: A WISDOT fracture (coarse), ASHTO T2 (WISDOT Modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T309.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T224, T265, ASTM D 1140.</p>	December 26, 2011	January 1, 2012	December 31, 2012
<p>GeoTest, Inc. 686 Progress Way Unit 4 Sun Prairie, WI 53590</p> <p>Jeff Anderson janderson@888geotest.com 414-321-8378</p>	<p>Aggregate: A WISDOT fracture (coarse), ASHTO T2 (WISDOT Modified), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T309, R39.</p>	December 26, 2011	January 1, 2012	December 31, 2012

<p>Gestra Engineering, Inc. 1626 W Fond Du Lac Avenue Milwaukee, WI 53205</p> <p>Jorge Martinez Jorge@gestrainc.com 414-933-7444</p>	<p>Aggregate: A WISDOT fracture (coarse), ASHTO T2 (WISDOT Modified), T11, T27, T89, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309.</p> <p>Soils: T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 15, 2011	January 1, 2012	December 31, 2012
<p>Giles Engineering Associates, Inc. N8 W22350 Johnson Drive Suite A1 Waukesha, WI 53186</p> <p>Charles S. Gresser, P.E. cgresser@gilesengr.com 262-544-0118</p>	<p>Aggregate: Fracture (Coarse agg.), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T277, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	November 14, 2011	January 1, 2012	December 31, 2012
<p>Great Lakes Soil & Environmental Consultants, Inc. * 600 Territorial Drive Suite G Bolingbrook, IL 60440</p> <p>Anshuman Balekai abalekai@greatlakessoil.com 630-754-8700</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability-WisDOT Test Method, AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104, AMRL Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 28, 2011	January 1, 2012	December 31, 2012

<p>Great Lakes Soil & Environmental Consultants, Inc. * 5004 W Ashland Way Franklin, WI 53132</p> <p>Anshuman Balekai abalekai@greatlakessoil.com 414-235-3170</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 28, 2011	January 1, 2012	December 31, 2012
<p>Gremmer & Associates, Inc. 120 North Wilshire Blvd Stevens Point, WI 54481</p> <p>Scott Hintz s.hintz@gremmerassociates.com 715-341-4363</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T152-Air Meter Calibration, T309.</p>	November 29, 2011	January 1, 2012	December 31, 2012
<p>Haas Sons, Inc. 203 E. Birch St. Thorp, WI 54771</p> <p>Linda Tichna Charlene@haas4.com 715-669-5469</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p>	December 20, 2011	January 1, 2012	December 31, 2012
<p>Independence Ready Mix Conc. Co. N35178 State Rd. 93 South Independence, WI 54747</p> <p>Mike Kupka indeereadymix@triwest.net 715-985-3118</p>	<p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p>	December 21, 2011	January 1, 2012	December 31, 2012

<p>Jewell Associates Engineers, Inc. 560 Sunrise Drive P.O. Box 995 Spring Green, WI 53588</p> <p>Ralph J. Liegel Ralph.liegel@jewellassoc.com 608-588-7484</p>	<p>Aggregate: AASHTO T2 (WISDOT modified), T248.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T152-Air Meter Calibration, T309.</p>	<p>December 5, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>John S. Olynick, Inc. N7918 Hwy 73 Gilman, WI 54433</p> <p>Jacquie Ludescher olynick@centurytel.net 715-668-5211</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T90, T248, T255.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T309.</p>	<p>November , 22, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>J Z Consulting N6098 CTH P Crivitz, WI 54114</p> <p>James L. Zwick jimzwick@webcntrl.com 715-854-2121</p>	<p>Aggregate: Fracture (coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p>	<p>December 6, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>KL Engineering, Inc. 5950 Seminole Centre Court Suite 200 Madison, WI 53711</p> <p>Lance Williston lwilliston@klengineering.com 608-663-1218</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T309.</p> <p>Soils: T88, T265.</p>	<p>December 6, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>KL Engineering, Inc. N7149 547th Street Menomonie, WI 54751</p> <p>Field Lab #1</p> <p>Chris Ehlert cehlert@klengineering.com 715-829-1266</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T309.</p> <p>Soils: T88, T265, ASTM D1140.</p>	<p>December 6, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>The Kraemer Company, LLC 820 Wachter Avenue Plain, WI 53577</p> <p>Mark Sander marks@tkcllc.com 608-546-2255X204</p>	<p>Aggregate: WisDOT fracture (coarse), Permeability–WisDOT Test Method, AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL’s Proficiency Sample Program.</p> <p>Soils: T89, T90.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>The Kraemer Company, LLC - Arcadia N25318 STH 93 Arcadia, WI 54612</p> <p>Mark Sander marks@tkcllc.com 608-546-2255 X220</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T90. T248, ASTM D4791.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>The Kraemer Company, LLC Elmwood Lab 810 South Public Street Elmwood, WI 54740</p> <p>Mark Sander marks@tkcllc.com 608-546-2255 X220</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability-WisDOT Test Method, AASHTO T2 (WisDOT modified), T11, T27, T248, T255, ASTM D4791.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>The Kraemer Company, LLC Mollett Lab E8020 State Highway 56 Viroqua, WI 54665</p> <p>Mark Sander marks@tkcllc.com 608-546-2255X220</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T248, T255, ASTM D4791.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>The Kraemer Company, LLC Williams Lab W11825 US 33 Portage, WI 53901</p> <p>Mark Sander marks@tkcllc.com 608-546-2255 X220</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T90, T248, ASTM D4791.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>The Kraemer Company, LLC Trailer Lab # 7663</p> <p>Mark Sander marks@tkcllc.com 608-546-2255X204</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T90, T248, T255, ASTM D4791.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>The Kraemer Company, LLC Trailer Lab # 7679</p> <p>Mark Sander marks@tkcllc.com 608-546-2255 X220</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T90, T248, T255, ASTM D4791.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>The Kraemer Company, LLC Trailer Lab # 7858</p> <p>Mark Sander marks@tkcllc.com 608-546-2255X220</p>	<p>Aggregate: WISDOT fracture (coarse), T11, T27, T84, T90, T248, T255.</p>	<p>November 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Langlade County HWY Dept. 1521 Arctic Street Antigo, WI 54409-2399</p> <p>Crystal Wells cwells@co.langlade.wi.us 715-627-6272</p>	<p>Aggregate: Fracture (Coarse Agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	November 21, 2011	January 1, 2012	December 31, 2012
<p>Lannon Stone Products Lab W220 N6799 Town Line Rd. Sussex, WI 53089</p> <p>Kevin Flasch kevinf@lannonstone.net 262-246-6911</p>	<p>Aggregate: Fracture (Coarse Agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p>	December 6, 2011	January 1, 2012	December 31, 2012
<p>Lincoln County HWY Dept. 100 S Cooper Street Merril, WI 54452</p> <p>Darren Lemke dlemke@co.lincoln.wi.us 715-536-0352</p>	<p>Aggregate: Fracture (Coarse Agg.), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Soils: T89, T90, T265.</p>	December 27, 2011	January 1, 2012	December 31, 2012
<p>Mann Brothers Portable Lab 1950 North Wisconsin Street Elkhorn, WI 53121</p> <p>Richard Erickson rerickson@mannbrosinc.com 262-723-5500</p>	<p>Aggregate: Fracture (Coarse agg.), Permeability-WisDOT Test Method, AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T152-Aggregate Correction.</p>	December 19, 2011	January 1, 2012	December 31, 2012

<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 608-779-6392</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104, AMRL's Proficiency Sample Program.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 1140.</p>	December 21, 2011	January 1, 2012	December 31, 2012
<p>Mathy Construction Company Arnot QC Lab American Asphalt 4807 Custer Road Steven's Point, WI 54481</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 715-341-1953</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	December 21, 2011	January 1, 2012	December 31, 2012
<p>Mathy Construction Company Mosinee QC Lab 1116 Happy Hollow Road Mosinee, WI 54455</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 715-693-5279</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269, T312.</p>	December 21, 2011	January 1, 2012	December 31, 2012
<p>Mathy Construction Company Fox Ridge QC Lab S. 4383 Hwy 12 Baraboo, WI 53913</p> <p>Erv Dukatz, PhD, P.E. edukatz@mathy.com 608-356-3742</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	December 21, 2011	January 1, 2012	December 31, 2012

<p>Mathy Construction Company Marshfield QC Lab 11928 Stadt Road Marshfield, WI 54449</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 608-384-9312</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p>	<p>December 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Mathy Construction Company New Richmond QC Lab 1190 Co. Rd. G New Richmond, WI 54017</p> <p>Erv Dukatz, PH.D, P.E. edukatz@mathy.com 715-246-7019</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>December 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Mathy Construction Company Brown's bottom QC Lab 12567 English Mill Road Dubuque, IA 52001</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 563-583-1902</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>December 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Mathy Construction Company Plant 87 Lab W5380 State Road 85 Eau Claire, WI 54701</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 715-835-0167</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>December 21, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Mathy Construction Company AMC Pit 31 QC Lab 3289 Jopke Road Eau Claire, WI 54702</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 715-830-5954</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p>	December 21, 2011	January 1, 2012	December 31, 2012
<p>Mathy Construction Company Plant 86 Lab 2601 Conoco Road La Crosse, WI 54601</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 608-783-2404</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p>	December 21, 2011	January 1, 2012	December 31, 2012
<p>Mathy Construction Company Hayward QC Lab 11154 N. Olson Road Hayward, WI 54843</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 715-234-2626</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete: T22, T23, T24, T119, T141, T152, T277, T309, R39.</p>	December 21, 2011	January 1, 2012	December 31, 2012
<p>Mathy Construction Company 915 Commercial Court Onalaska, WI 54650</p> <p>Portable QC Lab Trailers: 44-28, 44-29, 44-38, 44-41, 44-42, 44-43, 44-44, 44-45, 44-46, 44-62, 44-63, 44-95, 44-97, 44-98, 44-99, 44-103, 44-112, 44-113, 44-134, 44-152.</p> <p>Dr. Erv Dukatz, PhD, P.E. edukatz@mathy.com 715-779-6392</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	December 27, 2011	January 1, 2012	December 31, 2012

<p>MCC, Inc. 4905 W Prospect Ave Appleton, WI 54912</p> <p>Scott Paque Scptt.paque@murphinc.org 920-955-3639</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WISDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T277, T309, R39.</p> <p>Soils: T89, T90, T99.</p>	December 30, 2011	January 1, 2012	December 31, 2012
<p>Mead & Hunt Inc. * 6501 Watts Road Madison, WI 53719-2700</p> <p>Lew Kollmansberger Lew.kollmansberger@meadhunt.com 608-272-6380</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209.</p> <p>Concrete Mix: T23, T119, T141, T152, T309.</p> <p>Soils: T88, T99, T180, T224, T265, ASTM D422, ASTM D1140.</p>	November 15, 2011	January 1, 2012	December 31, 2012
<p>Michels Materials - Brownsville Lab 817 West Main Street Brownsville, WI 53006</p> <p>Lab #1</p> <p>Eric Zeinert ezeinert@michels-us.com 920-583-3132</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, AMRL's Proficiency Sample Program.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T89, T90, T99.</p>	December 13, 2011	January 1, 2012	December 31, 2012

<p>Michels Materials – Neenah Lab 700 Tullar Road Neenah, WI 54956</p> <p>Lab #2</p> <p>Eric Zeinert ezeinert@michels-us.com 920-727-1688</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Soils: T89, T90, T99.</p>	December 13, 2011	January 1, 2012	December 31, 2012
<p>Michels Materials – Waterloo Lab W11184 Hubbleton Road Waterloo, WI 53594</p> <p>Lab #3</p> <p>Eric Zeinert ezeinert@michels-us.com 920-478-2084</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Soils: T89, T90, T99.</p>	December 13, 2011	January 1, 2012	December 31, 2012
<p>Michels Materials Trailer Laboratories 817 West Main St. Brownsville, WI 53006</p> <p>Trailer Lab #s: D632, D741, D743, D1015 and D1021.</p> <p>Eric Zeinert ezeinert@michels-usa.com 920-583-3132</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability -WisDOT Test Method, AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Soils: T89, T90, T99.</p>	December 13, 2011	January 1, 2012	December 31, 2012
<p>Modern Ready Mix 4980 West 6th Street Winona, MN 55987</p> <p>Michael Kohner mikekohner@hotmail.com 507-454-5093</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152-Air Content, T152-Aggregate Correction, T309, R39.</p>	November 17, 2011	January 1, 2012	December 31, 2012

<p>Northeast Asphalt, Inc. Larsen 4515 City. Rd. 11 Larsen, WI 54947</p> <p>Karl Runstrom KRunstrom@payneanddolan.com 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 08, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Northeast Asphalt, Inc. De Pere 5118 Video Lane De Pere, WI 54115</p> <p>Karl Runstrom KRunstrom@payneanddolan.com 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 08, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Northeast Asphalt, Inc. Shawano W5660 Castle Road Shawano, WI 54166</p> <p>Karl Runstrom KRunstrom@payneanddolan.com 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 08, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Northeast Asphalt, Inc. Juneau W6134 Prospect Road Juneau, WI 53039</p> <p>Karl Runstrom KRunstrom@payneanddolan.com 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 08, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Northeast Asphalt, Inc. Green Bay Laboratory 1524 Atkinson Drive Green Bay, WI 54303</p> <p>Karl Runstrom KRunstrom@payneanddolan.com 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 08, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Northeast Asphalt, Inc. W6380 Design Drive Greenville, WI 54942</p> <p>Trailer Labs: 15410, 05411, 05412, 05413, 05521, 154102, 154034, 154029, 154190, 154195, 15232, 15228, 15274, 354073, 354075, 354104</p> <p>Karl Runstrom KRunstrom@payneanddolan.com 920-757-7585</p>	<p>Aggregate: Fracture (Coarse agg.), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	<p>November 08, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Northern Lakes Concrete Inc. 8075 County Hwy D Eagle River, WI 54521</p> <p>Dawn Pitlik dawnpitnick@yahoo.com 715-479-7488 ext 123</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T88, T100, T265.</p>	<p>December 9, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>OMNI Associates, Inc. * One System Drive Appleton, WI 54914</p> <p>Paul R. Eggen, PG, CET paul.eggen@omni.com 920-735-6900</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 5, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Park View Sand & Gravel LLC 31844 Washington Ave (Hwy D) Rochester, WI 53167</p> <p>Mark A. Franklin mafranklin@illinoismining.com 262-534-4347</p>	<p>Aggregate: WISDOT fracture (coarse), Permeability (WisDOT Test Method), AASHTO T2 (WISDOT Modified), T11, T27, T248, ASTM D4791.</p> <p>Soils: T88, T90, T99.</p>	<p>December 15, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-1 K & N Field Lab #154180 W259 N8150 Hwy 164 Sussex, WI 53029</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-524-1728</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-5 Fitchburg Lab 154138 6145 Cottonwood Trail Fitchburg, WI 53719</p> <p>Signe Reichelt sreichelt@payneanddolan.com 608-271-8617</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-2 Waukesha Field Lab #154137 N250 W233 Hwy F, Waukesha, WI 53186</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-524-1728</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Payne & Dolan, Inc. C-2 Waukesha Aggregate Lab # 154226 N250 W233 Hwy F, Waukesha, WI 53186</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-524-1728</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T255.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-7 Franklin Field Lab # 154140 6211 Rawson Ave Franklin WI 53132</p> <p>Signe Reichelt sreichelt@payneanddolan.com 414-423-2542</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-7 Franklin Aggregate Lab # 154225 6211 Rawson Ave Franklin WI 53132</p> <p>Signe Reichelt sreichelt@payneanddolan.com 414-423-2542</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T255.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. Portable Lab # 15408 34604 High Drive Waterford, WI 53185</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-534-4774</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 6, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Payne & Dolan, Inc. Portable Lab # 15333 677 Pleasant Valley Road West Bend, WI 53090</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-675-2218</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 6, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-12 Muskego Field Lab # 154141 W217 S8415 Crowbar Road Muskego, WI 53150</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-662-3366</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-31 Racine Field Lab # 154142 2020 Oakes Road Racine, WI 53406</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-884-7922</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. Kenosha Field Lab # 15377 1740 120th Ave. Kenosha, WI 53144</p> <p>Signe Reichelt sreichelt@payneanddolan.com 262-859-0569</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T248, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 6, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Payne & Dolan, Inc. Hustisford Field Lab # 15332 N2502 CTH R Hustisford, WI 53034</p> <p>Signe Reichelt sreichelt@payneanddolan.com 920-349-8584</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Payne & Dolan, Inc. C-6 Vienna Lab # 154139 5416 Easy Street Waunakee, WI 53597</p> <p>Signe Reichelt sreichelt@payneanddolan.com 608-849-8943</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T255.</p> <p>Asphalt Mix: CMM/QMP Sampling, T166, T209, T269, T312.</p>	<p>December 1, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Peters Concrete Company 1516 Atkinson Drive Green Bay WI 54303</p> <p>Perry Rose PCClab121@tds.net 920-494-3700</p>	<p>Aggregate: WISDOT Fracture (Coarse), AASHTO T2 (WISDOT Modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete: T22, T23, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T88, T89, T90, T99, T180, T265, ASTM D 422, ASTM D 1140.</p>	<p>November 14, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Pitlik and Wick, Inc. 8075 County Hwy D Eagle River, WI 54521</p> <p>Dawn Pitlik dawnpitnwick@yahoo.com 715-479-7488 ext 123</p>	<p>Aggregate: WisDOT fracture (coarse), Permeability-WisDOT Test Method, AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T90, T248, T255, ASTM D 4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Soils: T100, T265.</p>	<p>December 9, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Pitlik and Wick, Inc. 8075 County Hwy D Eagle River, WI 54521</p> <p>Trailer Lab</p> <p>Dawn Pitlik dawnpitnwick@yahoo.com 715-479-7488 ext 123</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T248, T255, ASTM D 4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1559, WisDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Soils: T88, T100, T265.</p>	<p>December 9, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>R E I Materials Laboratory 4080 N. 20th Avenue Wausau, WI 54401</p> <p>Tom Marschke tmarschke@reiengineering.com 715-675-9784</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T152-Air Meter Calibration, T309.</p> <p>Soils: T99, T265.</p>	<p>December 27, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>R.G. Huston Company Materials Lab 2561 Coffeytown Road Cottage Grove, WI 53527</p> <p>Dennis Richardson dennis@rghuston.com 608-255-9223</p>	<p>Aggregate: AASHTO T2 (WISDOT Modified), T11, T27, T248.</p>	<p>December 20, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>RJS Construction Group LLC/Johnson Materials Company I Clough Ave Superior, WI 54880</p> <p>Lab Trailer Nos. 2913, 2915.</p> <p>David M. Lemke dlemke@rjscompanies.com 715-394-7771</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T119.</p> <p>Soils: T88, T89, T90, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 13, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>River Valley Testing Corp. 1280 Parkview Road Green Bay, WI 54304</p> <p>Mark E. King, P.E. mking@rvtcorp.com 920-347-9040</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	December 2, 2011	January 1, 2012	December 31, 2012
<p>River Valley Testing Corp. 1060 Breezewood Lane, Suite 102 Neenah, WI 54956</p> <p>George Barker, P.E. gbarker@rvtcorp.com 920-886-1406</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling, WISDOT Test Method 1559, WISDOT Test Method 1560, T166, T209, T269, T312.</p>	December 22, 2011	January 1, 2012	December 31, 2012
<p>SCS Bt Squared 2830 Dairy Drive Madison, WI 53718</p> <p>Debra Nelson dnelson@scsengineers.com 608-224-2830</p>	<p>Aggregate: AASHTO T2 (WISDOT modified).</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T309.</p>	November 21, 2011	January 1, 2012	December 31, 2012
<p>Sheboygan County Highway Dept. 1211 N 23 St. Sheboygan, WI 53081</p> <p>gottoamg@co.sheboygan.wi.us 920-459-3822</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p>	November 11, 2011	January 1, 2012	December 31, 2012

<p>Soils & Engineering Services, Inc. * 1102 Stewart Street Madison, WI 53713-4648</p> <p>Duane E. Reichel, P.E. duane@soils.ws 608-274-7600</p>	<p>Aggregate: WisDOT Fracture (Coarse agg.), Permeability – WisDOT Test Method, AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T104.</p> <p>Asphalt Mix: CMM/QMP Sampling, WisDOT Test Method 1560, T166, T209, T269.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	November 18, 2011	January 1, 2012	December 31, 2012
<p>T3 Concrete Testing, Inc. 1510 N. County Club Pkwy Suite G Elkhorn, WI 53121</p> <p>James P. Blaine Jr. jim@t-3testing.com 262-723-3131</p>	<p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T24, TT97, T119, T141, T152, T198, T309, R39.</p>	December 16, 2011	January 1, 2012	December 31, 2012
<p>Team Engineering, Inc. 240 Main Street, P.O. Box 117 Loganville, WI 53943</p> <p>Steven Alt salt@teamenginc.com 608-727-2146</p>	<p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T152-Air Meter Calibration, T309.</p>	December 2, 2011	January 1, 2012	December 31, 2012

<p>Terracon Milwaukee (Franklin) Office 9856 South 57th Street Franklin, WI 53132</p> <p>Jim Tippett jetippett@terracon.com 414-423-0255</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T180, T265, ASTM D 422, ASTM D 1140.</p>	December 6, 2011	January 1, 2012	December 31, 2012
<p>Toki & Associates, Inc. 7100 W. Fond Du Lac Ave. Suite 201 Milwaukee, WI 53218-3847</p> <p>Olaitan Olapo toki@tokiandassociates.com 414-463-2700</p>	<p>Aggregate: WisDOT fracture (coarse), WisDOT Permeability, AASHTO T2 (WisDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T103, T104.</p> <p>Concrete Mix: T22, T23, T24, T119, T141, T152-Air Content, T152-Aggregate Correction, T231, T309, R39.</p>	November 16, 2011	January 1, 2012	December 31, 2012
<p>Trierweiler Construction & Supply Co., Inc. 406 East 29th Street, P O Box 1236 Marshfield, WI 54449</p> <p>Michael Hammitt lab@trierweilerco.com 715-223-5916</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T309, R39.</p>	December 12, 2011	January 1, 2012	December 31, 2012

<p>Trierweiler Construction & Supply Co., Inc. 406 East 29th Street, P O Box 1236 Marshfield, WI 54449</p> <p>Trailer Lab</p> <p>Michael Hammitt lab@trierweilerco.com 715-223-5916</p>	<p>Aggregate: AASHTO T2 (WISDOT modified), T11, T27, T248, T255.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T309, R39.</p>	<p>December 12, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Twin Ports Testing Inc. * 1301 North Third Street Superior, WI 54880</p> <p>Greg g A. Paterson Gregg.patterson@twinportstesting.com 715-392-7114</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T22, T23, T24, T97, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>November 18, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Vulcan Materials Company-Franklin Lab 5713 W Rawson Avenue Franklin, WI 53132</p> <p>Gina M. Parisi-Luedtke parisig@vmcmail.com 414-421-1518</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p>	<p>December 19, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Vulcan Materials Sussex Lab N52 W23096 Lisbon Rd. Sussex WI 53089</p> <p>Gina M. Parisi-Luedtke parisig@vmcmail.com 262-246-3591</p>	<p>Aggregate: WisDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T248, T255, ASTM D4791.</p>	<p>December 19, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Wabasha Sand Gravel & Ready Mix 905 Church Ave Wabasha, MN 55981</p> <p>Mike Kohner mikekohner@hotmail.com 651-565-3610</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT Modified), T11, T27, T248, T255, ASTM D4791.</p> <p>Concrete Mix: T23, T119, T141, T152-Air Content, T152-Aggregate Correction, T309.</p>	<p>November 17, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Westbrook Materials Laboratory 619 E. Hoxie St. & E4751 Rt. 2 Hwy 14 W, Spring Green, WI 53588</p> <p>Nancy Ringelstetter nringelstetter@westbrookeng.com 608-588-7866</p>	<p>Aggregate: AASHTO T2 (WisDOT modified), T11, T27, T89, T90, T248, T255, ASTM D 4791.</p> <p>Concrete Mix: T22, T23, T97, T119, T141, T152, T198, T231, T309, R39.</p> <p>Soils: T89, T99, ASTM D1140.</p>	<p>December 16, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Wisconsin Testing Laboratories, LLC W140 N5886 Lilly Road Menomonee Falls, WI 53051</p> <p>Jeffery G. Smith jsmith@witestlab.com 262-252-3300</p>	<p>Aggregate: WISDOT fracture (coarse), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Asphalt Mix: CMM/QMP Sampling.</p> <p>Concrete Mix: T22, T23, T119, T141, T152, T231, T309, R39.</p> <p>Soils: T87, T88, T89, T90, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 27, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
<p>Yahara Materials, Inc. 6117 CTH K Waunakee, WI 53597</p> <p>Trailer Labs # 2263.</p> <p>Kevin Stuart KEVIN@YAHARA.COM 608-445-9643</p>	<p>Aggregate: Fracture (Course Agg.), AASHTO T2 (WISDOT modified), T11, T27, T89, T90, T248, T255, ASTM D4791.</p> <p>Soils: T88, ASTM D 422, ASTM D 1140.</p>	<p>December 23, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>

<p>Yahara Materials, Inc. 315 Moravian Valley Rd Suite #9 Waunakee, WI 53597</p> <p>Kevin Stuart KEVIN@YAHARA.COM 608-849-4162</p>	<p>Aggregate: Fracture (Course Agg.), AASHTO T2 (WISDOT modified), T11, T27, T84, T85, T89, T90, T248, T255, ASTM D4791.</p> <p>Aggregate Quality Testing: Fracture (WisDOT CMM 8.60), T89 Using T146 Method A for Prep of P-4, T90 Using T146 Method A for Prep of P-4, T84, T85, T96, T103, T104, AMRL Proficiency Sample Program.</p> <p>Soils: T87, T88, T89, T90, T92, T99, T100, T180, T224, T265, ASTM D 422, ASTM D 1140.</p>	<p>December 23, 2011</p>	<p>January 1, 2012</p>	<p>December 31, 2012</p>
--	---	--------------------------	------------------------	--------------------------

* Indicates laboratory is AASHTO accredited.